



MS3101



Pin Assignment

Pin NO.	Signal Name
1	+ OUTPUT 2
2	- OUTPUT 2
3	N.C.
4	P(+)
5	N(-)
6	GND
7	TC +
8	TC -
9	N.C.
10	N.C.
11	+ OUTPUT 1
12	- OUTPUT 1

Pin Location



単位:mm