


MS3971

コネクタカバー装着図



Pin Assignment

SOCKET	PIN NO.	SIGNAL NAME
1	1	TC+
	2	TC-,CJ COM
	3	N.C.
	4	CJ用電源
	5	CJ +
	6	N.C.
2	1	+ OUTPUT-1
	2	- OUTPUT-1
	3	+ OUTPUT-2
	4	- OUTPUT-2
	5	+ POWER DC24V
	6	- POWER DC24V
	7	N.C.
	8	N.C.
	9	F.G
	10	N.C.

単位:mm